



FIG. 1




09419570-0390
T06220-0290T860

FIG. 2



TOP SECRET

FIG. 3



091670-0296T850

FIG. 4





FIG. 5



TABLED-0236T860

FIG. 6




FIG. 7




FIG. 8

FIG. 8

URL

TROUBLE DB INPUT WINDOW

OCCURRENCE DATE ~ 404

TYPE OF APPARATUS ~ 401

SUBJECT ~ 403

SERIAL NUMBER S/N ~ 402

DEGREE OF URGENCY ~ 405

SYMPTOM

LED IS KEPT FLICKERING AFTER POWER-ON

406

REMEDY

POWER ON AGAIN
(PRESS RED BUTTON IN ACTIVATION)

407

PROGRESS

INTERIM HAS BEEN DONE

408

SEND

RESET

416

417


418

LINK TO RESULT LIST DATABASE

SOFTWARE LIBRARY

OPERATING GUIDE

FIG. 9



```

graph TD
    S11[OXIDATION  
S11] --> S12[CVD  
S12]
    S12 --> S13[FORM ELECTRODE  
S13]
    S13 --> S14[IMPLANT ION  
S14]
    S14 --> S15[RESIST PROCESSING  
S15]
    S15 --> S16[EXPOSURE  
S16]
    S16 --> S17[DEVELOPMENT  
S17]
    S17 --> S18[ETCHING  
S18]
    S18 --> S19[REMOVE RESIST  
S19]
    S19 --> REPEAT[REPEAT]
    REPEAT --> S11

```